


P.S. - Possible the PL monitor will jitter -
try changing the 100K Ω resistor here to $\approx 39K \Omega$

CONVERTING THE FD-68 RGB FOR POSITIVE SYNC MONITORS



REMOVE THE LS-367 AND REPLACE WITH
THE ENCLOSED ASSEMBLY.

INSERT ASSEMBLY WITH THE NOTCH AT
THE SAME CORNER AS THE DOT. IF YOU
RE-INSTALL THE LS-367, BE SURE TO
PLACE IT IN THE SAME DIRECTION.